

F. C.




FIG.2








FIG.3









10/549754

8/8			
π	I	0	0
	I	+	I
$\pi/2$	0	+	0
	+	+	+
0	+	0	0
	+	1	1
-π/2	0	!	0
	1	î	+
π-	ı	0	0
PHASE SHIFT	S7I	870	CONTROL DIRECTION

FIG.8